



Electronic Positive Response (EPR) System Changes NEVADA ONLY



Code description changes and new codes will be active **July 1, 2021**.
Codes identified to be deleted will be deleted on **September 1, 2021**.

EPR Code	Code Description	Changes Made
1	CLEAR - NO CONFLICT	No changes made
2	CLEAR - NO CONFLICT BUT PRIVATELY OWNED UTILITY ON PROPERTY - CONTACT PRIVATE UTILITY OWNER	Change description to: NO CONFLICT BUT PRIVATELY OWNED UTILITY IN AREA - CONTACT PRIVATE UTILITY OWNER <i>(This code can be used to identify utilities in ground that are not yet accepted by utility operator)</i>
3	EXISTING MARKINGS ADEQUATE	Change description to: SITE VISITED - EXISTING MARKINGS ADEQUATE
4	NO MARKINGS REQUESTED	No changes made
10	LOCATE AREA MARKED	No changes made
11	LOCATE AREA MARKED BUT ABANDONED FACILITIES MAY BE IN THE AREA	No changes made
12	LOCATE AREA MARKED UP TO PRIVATE OWNED FACILITY - CONTACT PRIVATE UTILITY OWNER FOR LOCATE	Change to: LOCATE AREA MARKED UP TO PRIVATE OWNED FACILITY - CONTACT PRIVATE UTILITY OWNER FOR LOCATE (https://www.nulca.org/DirectoryMap/CompanyDirectoryMap)
13	LOCATE AREA MARKED UP TO PRIVATE PROPERTY	Code will be deleted: Use code 12 instead for this purpose
14	PARTIALLY MARKED - MORE TIME IS NEEDED	No changes made
20	BAD ADDRESS/INCORRECT STREET/LOCATION INFO	Change to: BAD ADDRESS/INCORRECT STREET/LOCATION INFO - NEW TICKET REQUIRED
21	NO ACCESS TO LOCATE AREA - RESEND TICKET REQUESTED	Change to: UNABLE TO LOCATE - ADDITIONAL ACCESS REQUIRED - NEW TICKET REQUIRED
22	NO DELINEATION. -RESEND TICKET REQUESTED	Code will be deleted: Use code 24 instead for this purpose
23	DELINEATED AREA DOES NOT MATCH LOCATION REQUEST - RESEND TICKET REQUESTED	Code will be deleted: Use code 24 instead for this purpose
24	WHITE PRE-MARKINGS UNCLEAR - NEW TICKET REQUIRED	New code and description
30	CONTACT FACILITY OWNER FOR FURTHER INFO	Code will be deleted: No longer needed
31	REQUIRES STAND BY AT TIME OF EXCAVATION - CONTACT FACILITY OWNER	No changes made
32	VISIBLE OR EXPOSED FACILITY - CONTACT FACILITY OWNER IF CROSSING	Code will be deleted: No longer needed
33	HIGH PRIORITY LINE IN AREA	Change to: MARKED HIGH PRIORITY LINE IN AREA
34	FIELD MEET REQUIRED	Change to: FIELD MEET REQUIRED - LOCATOR WILL SCHEDULE
40	EXCAVATOR COMPLETED WORK PRIOR TO DUE DATE	Change to: NO MARKS NEEDED - EXCAVATOR CONFIRMED WORK COMPLETED
41	EXCAVATOR NO SHOW FOR MEET	No changes made
42	EXCAVATOR CANCELED REQUEST	No changes made
50	NEGOTIATED MARKING SCHEDULE	No changes made
52	UNABLE TO LOCATE USING STANDARD LOCATING TECHNIQUES	Change to: TROUBLE LOCATE - ADDITIONAL TIME IS REQUIRED
54	COULD NOT CONTACT - TICKET NOT LOCATED - PLEASE CONTACT UTILITY DIRECTLY & UPDATE CONTACT INFO WITH 811	New code and description
80	EXTRAORDINARY CIRCUMSTANCES EXIST - NO LOCATE DUE TO WEATHER/EMERGENCY CONDITIONS	No changes made

Guide

	No Changes Made
	Changes Made to Code/Description

	Code Deleted
	New Code Added